Dredge: SAGLE ONE

Project: FRESPORT, TX

DAILY REPORT
Date 20 / JULY / 01 Load Numbers 1 ~ 15
Area(a) Warked Santina 2 20000 N OS'11-11/
Weather Conditions (incl. sea conditions) PCLOUDY U AIRS BST 2-5 PAIN IN AM HOURS
Range of Water Temp., Surface 29-30°C Below Mid-Depth 29-30°C
Condition and Effectiveness of Screening good [condition], effectiveness poor (varies
load - to - load) due to chogging of boxes a clay).
Are there incidents involving endangered or protected species? YES
Comments (details of turtle takes or whale sightings, dredged material, screening, biological by-catch, etc.):
Dredge Eagle One began work in Freeport, Tx at 0315 or
20 July 01. Endangered species observers Kirsten Dahlen and
Brian Fedorko are on board.
Dredged material is silt and clay with small amounts of grass and
rocks. Abiotic debris includes: chain, scrap metal, shrimp nets, rope, fishing line, straps
plastie debris,
Bione debros is minimal, industing undertified seawerd sargassum and
feathery by 0800
There were no incidents involving threatened, endangered or protected
Species,
Bridge Watch Summary
Species # of Animals Time / Location / Comments
Tursiaps truncatus 2 0712 SECTION 2
TE 6-8 0824/CHANNEL BY SECTION 2 - JETTLES
TE 4 1215 / dumpsit
TE 8-14 1420-1440/DUMR/FEEDING, RACING + ACROBATICS
Observer(s) on duty Kirsten Dahlen + Brian Fedorko.

Dredge: EAGLE ONE

Project: FREEPORT ZNIKANCE CHANNEL, TX

Date 21 / Ju	4 /01	Load Numbers 16 - 36
Area(s) Workeds conc	NS 2+6 STA	90th 40th 28°55 N 98°16 W Sect 6 - Sta - 190th -
Weather Conditions (in	ncl. sea conditions) વહ	or => P. Cloudy BSS Z-3 Le airs
		D.5°C Below Mid-Depth 29-30.5°C
		od. Effectiveness reduced on 5 bods as
		loading.
		or protected species? YES
	nvolving endangered (
Comments (details of	turtle takes or whale sig	ghtings, dredged material, screening, biological by-catch, etc.):
DREDGED MATE	ERIAL IS SILT & CLAY	Y WITH SMALL AMOUNTS OF GRASS AND ROCKS. ABIOTIC
DEBRIS INCLUDES PL	ASTIC STRAPPING, RO	SPE, SHRIMP NETS, MESH BAGS, MOND FILAMENT, TIRES CHAIN,
BY-CATCH INC	LUDES: BLUE CRAB	3 (CALLINECTES SAPIONS), FEATHERY BRYDROA.
There was	re no incidents	involving threatened, endangered or protected
Lector.		
TE	2-4	1615 / C-broy / Fedire
		Bridge Watch Summary
Species	# of Animals	Time / Location / Comments
TUBLIDES TRUVCATUS	1-2	0654 SECTION 2
TE	9-12	0740 (en route to dump
TE	6-8	0915-0930/ In channel @ dig site
TE	4-8	1280-1230 CHANNEL , FRET. 2 / FERRING
TE	6-10	1330 ISEG= 2 /FEEDING
TE Observer(s) on duty_	KIESTEN DAHLEN	AND BRIAN FEDORKO

Dredge: EAGLE ONE

Project: FRISPORT ENTRANCE CHANNEL TK

WEEKLY SUMMARY

Dates 20 /204 / 01 - 21 /204 / 01 Load Numbers 01 ~ 36
Range of Water Temp., Surface 29-30.5°C Below Mid-Depth 29-30.5°C
Areas Worked (lat/longs, stations) Sections 2+6 STA -904-40; 1007 28 55 N 95 16 W
Are there incidents involving endangered or protected species? YES
Comments (turtle takes, whale sightings, effectiveness of screening, by-catch, material, other info):
PREDGE EAGLE ONE BEGAN DIGGING AT THE FREEPORT ENTRANCE CHANNEL AT
0315 H , 20 JULY 01. ENDANGERED SPECIES OFSERVERY KIRSTEN DANLEN + BRIAN
FERORKO ON BOARD.
DREDGED MATERIAL IS SILT AND CLAY WITH SMALL AMOUNTS OF GRASS AND
ROCK ADIOTIC DEBRIS INCLUDES CHAIN, SHRIMP NETS, SCRAP METAL, PLASTIC STRAPPING ROPE,
MESH BAGS MONOFILAMENT, TIRES, CLOTH
BIOTIC BY CATCH INCLIDES: FEATHERY BRYOZDA, BILLE CRAB (CALLIPECTES JAPIDUS)
Screening Efficiency reduced on some (5-10) loads as inflaw doors agreed
during booking due to clogging with clay.
THERE WERE NO INCIDENTS INVOLVING THREATENED, ENPANGERER OR PROTECTED SPECIES.
,
Bridge Watch Summary
Date Various Species and Respective Number Comments
20 / JULY TURGIOFS TRUPGATUS (20-28) ALL DAY ALL AREAS / ACTIVE
21 / JULY TURSIONS FUNCATION (42-42) ALL DAY (ALL AREAS / ACTICUS
<u> </u>
Observers on duty KIRSTEN PAHLEN + BRIAN FEDORKO

Project: Freeport Entrance Channel, TX

Date 22 / July / 01 Load Numbers 37 - 63.
Area(s) Worked Sections 2+6 Stations -90" 40" -190" 6-140" 28-44 N 95-16W
Area(s) Worked Sections 2 + 6 Stations 15 (SW 5-6)
" (" al and conditions) & Claudy () a Grandy
Below Mid-Depth 21 Joseph
Boxes aboved offer it Region
is also for Mid without appeal from war
due to mechanical problem. Sorcering efficiency reduced in loads
Are there incidents involving endangered or protected species?
the standard takes or whale sightings, dredged material, screening, biological by-catch, etc.):
Dredged moterial is day and silt thiotic debris includer; shring
ness manufilament, rape, much bogg, plantic, scrap mutal, fish net, crab traps
cable.
By-coatch includes a feathery 1970 book One sub-adult careta careta (loggerhead) was seen from the bridge in section two, swimming west. There were no includents involving threatmed enlargered or protected species.
Bridge Watch Summary
Species # of Animals Time / Location / Comments
Species (S Mes Sect. 6
Tursiaps trincatur 6-8 20-25 0840-0930 Feet 2 & dump
a the head west
Saretta Caretta (loggerhead) 1 1517-Sect 2 - Surfaces to dearrow Gedwing 1715- en route to during feeding
Observer(s) on duty Kiroton Dahlen & Brian Fedorks.

Project: Freeport Entrance Channel, TX

Area(s) Worked \action 2		Load Numbers 64 - 92
(c) HOMOWAY Z	+ 6 Sta - 90tos	to -40 too and - 190 to -140 too 28.55 N 95°16 W
Weather Conditions (inc	l. sea conditions) <u>(</u>	P. Choudy 1398 1-2 Lt SW wind (5-6 KH)
		Below Mid-Depth _ 28 -
Condition and Effectives	ness of Screening 🤇	pareening condition is generally good. Effectiveness
		ase see attached.
Are there incidents inv	olving endangered	I or protected species? YES
Comments (details of tur	rtle takes or whale s	sightings, dredged material, screening, biological by-catch, etc.):
Dredged materia	al is silt with	increasing amounts of day. Abiotic debris
includes: shrimp n	ets fish nets	monofilament, mesh bags milk crates crab
trap; plastic, scro	ap metal, clot	h, 5 gallon bucket, rope, wood, plastic juice container,
rel cable, rug		
By-catch include	es: Bryozoa,	Spot Cleiostomus Kanathus, Kuthal whelk egg
		ontified eels, sargassum, Lightning whelks (B. contrarium)
One juvenile o	r sub-adult	Caretta coretta (loggerhead) was seen
surfacing to brea	the in the	dimp area.
There were n	a incidents in	valving threatened or endangered species.
		Bridge Watch Summary
Species	# of Animals	Time / Location / Comments
Tursi ops truncatus	3-5	0815/en route to dump
TE	10-15	1400-1420 / Setion 2 / Feding
	12-16	1530-1540 (channel / bow-riding
14		
Cc		1940 - Syrfaced in dump- juv. or subadult

Dredge: Engle 1
Project: Freeport Entrance Channel, TX

Area(s) Worked	Date 23 / Ju	4 /01	Load Numbers conti	nu ed	
Weather Conditions (incl. sea conditions) Range of Water Temp., Surface Below Mid-Depth Condition and Effectiveness of Screening Are there incidents involving endangered or protected species? YES NO Comments (details of turtle takes or whale sightings, dredged material, screening, biological by-catch, etc.): Screening effectiveness is reduced on many loads due to heavy clagging with clay and problems with hydraulies and rams on inflow box doars. The doors on the mid-part inflow box slipped agen (-12' during loading with) additional repairs were completed during load #77. Step mip inflow has additional repairs were completed during load #77. Step mip inflow has slipped agen (-12' during loading and is closed on observer request. Section to material is mainly clay, which leads to clagging of inflow baxas within minutes of load starting times. Doors are appeared, cleared preclosed and routinely re-slag within several minutes. Screening effectiveness on some loads in Section to it essentially remained to problems with clagging and reduced thank (ACOE) to keep them informed of problems with clagging and reduced screening effectiveness at the Feepart site. Bridge Watch Summary	Area(s) Worked				
Are there incidents involving endangered or protected species. Comments (details of turtle takes or whale sightings, dredged material, screening, biological by-catch, etc.): Screening effectiveness is reduced on many loads due to heavy clagating with clay and problems with hydraulies and rank an inflow box doars. The doors on the mid-part inflow box slipped open by 2 during loading with additional repairs were completed during load #77. Stro mip inflow door also slipe open occasionally during loading, and is closed as observer request. Section to material is mainly clay which leads to clagating of inflow bakes within minutes of load starting times. Doors are opened, eleaned preclased and routinely re-class within several minutes. Screening effectiveness on tome loads in Section to is essentially zero. Observer contacted their slay (Coastwise Consulting) and Rob thuch (ACOE) to keep them informed of problems with clagging and reduced screening effectiveness at the Freeport site. Bridge Watch Summary	Weather Conditions (in Range of Water Temp.	ncl. sea conditions), Surface	Below Mid-	Depth	
Screening effectiveness is reduced on many loads due to Neavy chagging with clay and problems with hydraulies and name an inflow box doors. The doors on the mid-part inflow box slipped open 6-12' during loading with additional repairs were completed during load #77. Step Mip inflow door. Also slipe open occasionally during loading, and is closed as observent request. Section to material is mainly clay, which leads to clagging of inflow baxes within minutes of load starting times. Doors are opened, aleared preclased and routinely re-slog within several minutes. Screening effectiveness on some loads in Section to is essentially zero. Observers contacted this slay (Coastwise Consulting) and Rob Hauch (AKOE) to keep them informed of problems with clagging and reduced screening effectiveness at the Freeport site. Bridge Watch Summary					
clay and problems with hydraulics and rank are trible of actions of the mid-part inflaw box slipped open 6-12' during loading with additional repairs were completed during load #77. STED mip without door also slipe open occasionally during loading, and is closed as observer request. Section to material is mainly clay, which leads to clagating of inflaw baxes within minutes of load starting times. Doors are opened, cleared preclased and routinely re-class within several minutes. Screening effectiveness on some loads in Section to is essentially zero. Observers contacted thris slay (Coastwise Consulting) and Rob thuch (ACOE) to keep them informed of problems with clagging and reduced screening effectiveness at the Freeport site. Bridge Watch Summary	Comments (details of	turtle takes or whale s	sightings, dredged material, s	screening, blowg	car by-carees, order,
clay and problems with hydraulics and rank are interested active and coors on the mid-part inflow box slipped open hors' during loading with additional repairs were completed during load #77. Step mip without door also slipe open occasionally during loading, and is closed as observer request. Section to material is mainly clay, which leads to clagating of inflow baxes within minutes of load starting times. Doors are opened, cleared preclased and routinely re-class within several minutes. Screening effectiveness on some loads in Section to is essentially zero. Observers contacted thris slay (Coostwise Consulting) and Rob thuch (ACOE) to keep them informed of problems with clagging and reduced screening effectiveness at the Freeport site. Bridge Watch Summary	Screening eff	convenos is red	luced on many loads	due to Mean	in clagging with
doors on the mid-part inflow box slipped open 6-12 during loads with additional repairs were completed during load #77. STED MID inflow four additional repairs were completed during load #77. STED MID inflow four also slipe open occasionally during loading and is closed as observer request. Section to material is mainly clay which leads to clogging of inflow baxes within minutes of load starting times. Doors are opened, cleared preclased and routinely re-slag within several minutes. Screening effectiveness on some loads in Section to is essentially zero. Observers contacted their slay (Coastwise Consulting) and Rob Hauch (ACOE) to keep them informed of problems with clagging and reduced screening effectiveness at the Freeport site. Bridge Watch Summary	clair and ord	olems with hus	raulies and ranks	OLC CLUM	OUR BUCK!
additional repairs were completed during load TT. STEP into minutes and also slipe open occasionally during loading, and is closed as absencent request. Section to material is mainly clay, which loads to clagging of inflaw baxes within minutes of load starting times. Doors are opened, cleared preclased and routinely re-class within several minutes. Screening effectiveness on some loads in Section to it essentially zero. Observers contacted chris slay (Coastwise Consulting) and Rob thurch (ACOE) to keep them informed of problems with clagging and reduced screening effectiveness at the Freeport site. Bridge Watch Summary	-1-000 +he M	aid . part inflaud	box slipped open k	5-15 AM. WA	rogan ca www
Also slipe open occasionally during loading, and is elased at asserver region. Section 6 material is mainly clay, which leads to clagging of inflaw bakes within minutes of load starting times. Doors are opened, aleared preclused and routinely re-class within several minutes. Screening effectiveness on some loads in Section 6 is essentially zero. Observers contacted chris slay (Coastwise Consulting) and Rob Hauch (ACOE) to keep them informed of problems with clagging and reduced screening effectiveness at the Freeport site. Bridge Watch Summary	additional repair	z were comple	ted during load	TT. SIED IN	the tractions was
Section to material is mainly clay, which leads to clagging of interest backs within minutes of load starting times. Doors are opened, cleared preclased and routinely re-class within several minutes. Screening effectiveness on some loads in Section to it essentially zero. Observers contacted Chris Slay (Coastwise Consulting) and Rob thuch (ACOE) to keep them informed of problems with clagging and reduced screening effectiveness at the Freeport site. Bridge Watch Summary	No die over	occasionally du	ring loading, and i	८ डाका ट्या पर	Washing!
within minutes of load starting times. Doors are opened, cleared freehold and noutinely re-cloq within several minutes. Screening effectiveness on some loads in Section 6 is essentially zero. Observers contacted thris slay (Coartwise Consulting) and Rob Hauch (ACOE) to keep them informed of problems with clagging and reduced screening effectiveness at the Freeport site. Bridge Watch Summary	Section 6 m	oterial is main	ly clay, which lead	12 to clagging	of introd paker
Some loads in Section 6 is essentially zero. Observers contacted their slay (Coastwise Consulting) and Rob thuch (ACOE) to keep them informed of problems with clagging and reduced screening effectiveness at the Freeport site. Bridge Watch Summary	within minutes	of land star	ting times. Doors a	no obcincol,	created treemsea
Some loads in Section 6 is essentially zero. Observers contacted thris slay (Coastwise Consulting) and Rob thuch (ACOE) to keep them informed of problems with clagging and reduced screening effectiveness at the Freeport site. Bridge Watch Summary	and routinely	re- clag within	n several minutes. S	icreening eff	ectiveness on
Observers contacted thris slay (Coastwise Consisting) and Lab thuch (ACOE) to keep them informed of problems with changing and reduced screening effectiveness at the Freeport site. Bridge Watch Summary	one shoots in	Section 6 is	essentally zero.		
thuch (ACOE) to keep them informed of problems with changing and reduced screening effectiveness at the Freeport site. Bridge Watch Summary	Objections of	contacted ch	ris Slay (Coastwise	Consisting	and kab
Bridge Watch Summary Time / I postion / Comments	Hauch (ACOE)	to keep them	informed of problems	with clage	ing and reduced
Bridge Watch Summary	screening effective	eness at the f	reepart site.		
Species # of Animals Time / Location / Comments	J		Bridge Watch Summary		į
	Species	# of Animals	Time / Location / Con	nments	
Observer(s) and duty Kirsen Dahlen and Brian Fedors					

Dredge: <u>Eagle 1</u>
Project: <u>Freeport Entrance Channel</u>, TK

Date 24 / July / 01 Load Numbers 93 - 121
Area(s) Worked Sect. 2+6 Sta -90th -40th +-190th -140th 28.55N 95016W
Weather Conditions (incl. sea conditions) & cloudy, am rain, It SW wind, BSS 1-2
Range of Water Temp., Surface 29-30.5°C Below Mid-Depth 29-30.5°C
Condition and Effectiveness of Screening Condition is generally good; effectiveness range
from good to poor; especially poor to non-existent in sect. 6 where
material is heavy clay. Mid-STBO inflow door slips open 6-12' on some hoads.
Are there incidents involving endangered or protected species? YES
Comments (details of turtle takes or whale sightings, dredged material, screening, biological by-catch, etc.):
Dredged material is silt with increasing amounts of clay.
Abiotic debris includes: shrimp + fish nets, mush bags, rope, plastic bags
floor mats, wire, cloth, milk crate, monofilament line, wood, rubber strag
able
By-catch includes: feathery bryozaa, songassum, lightning whelk egg
Cases (Busy contravium)
There were no incidents involving threatened, endangered or protected
Species.
Bridge Watch Summary
Species # of Animals Time / Location / Comments
Tursiops truncatus 7-10 1130 - dumpsite
Observer(s) on duty Kinten Dahlen + Brian Fedorico

Dredge: Engle 1
Project: Freeport Entrance Channel, TX

Date 25 / Ju	my / 01	Load Numbers 122	-149	
Area(s) Worked Sect	ions 2,3+6 5	ta 90th 0 to and -190th.	6 -140th 28°S	SN 95°16W
		Mostly cloudy an rain		
Range of Water Temp.	Surface 29-3c	Below Mid-D	enth 29 - 30	Č.
		ondition is good; effe		
		ay on some bods.	CFF C. CIT OW	thom good
	<i>J</i> 33 1 2 0	my or some made.		
Are there incidents in	volving endangered	or protected species?	YES	NO
Comments (details of to	urtle takes or whale s	sightings, dredged material, scre	eening, biological	by-catch, etc.):
		ay. Abionic debris inclu		
		Puc pipe, crab traps, fish		
cloth Fillow, street	est.		1,000	
By-cotch incl	ides sargassum	, tarterest effices (Differ	- Carl	nery bryozoa
There were special.	na incidents in	wolving threatened, f	entected or	endangereb
	<u>]</u>	Bridge Watch Summary		
Species	# of Animals	Time / Location / Commer	nts	
Tursiops truncatus	4-8	1230 Detties /FEC	4.2.	
				······
Dbserver(s) on duty <u>Ki</u>	rsten Dahlen	+ Brion Fedorko		

Dredge: Eagle 1 Project: Freeport Entrance Channel, TX

Date 26 / Jul	<u>4 /01</u>	Load Numbers 159 7 17	-6	
Area(s) Worked Secr :	2,3+ 6 Sta 1	0 to 740th - 40th - 90th, -140	ر ۱۹۵ سر ۱۹۵ مساد	28°55N 90-16W
Weather Conditions (in	cl. sea conditions)	in in any firm cloudy u	15rd, SE 5-11	0 1822 [-3
Range of Water Temp.,	Surface <u>29.5 - 8</u>	R9°C Below Mid-Dep	th29.5 - 2°	7°C
		redition is generally go		
		heavy clay in sections		
Are there incidents in	volving endangered	or protected species?	YES	NO
Comments (details of to	utle takes or whale s	ightings, dredged material, scree	ning, biological	by-catch, etc.):
Dredged mote	rial is silt a	and day Abionic debris	includes fi	sh + shring now
		flament, gloss bottles, alus		
		straps, burgee oards, c		
By-catch incl	udes: feathery	puloson sorbassam	Lightraing	whelk egg _
coses (Bushow o	nuarium)			
There were	na incidents	involving protested three	attened or	endong red
Secter.				
		Bridge Watch Summary		
Species	# of Animals	Time / Location / Comment	S	
Tursiaps truncation	1-2	0903/bay 4		
TE		0930/ so rouse to dup		
Observer(s) on duty 1	iota Dohlen o	nd Brian Federko		

Project: Freceart Entrance Channel

Date 27/5	July / 01	Load Numbers <u>177 - 199</u>	
Area(s) Worked	2,3+6 Sta.0	0 to-40 to -40 to-90 to 140 to - 190 to 28. 4cts 95-0 16W	1
Weather Conditions (i	incl. sea conditions)	rain in aim, overcost >> M. Chudy winds NS-15 BSS	— }
Range of Water Temp	o., Surface 29°	°C Below Mid-Depth 29°C	
Condition and Effective	veness of Screening	Condition of screening is generally good. Some	
effectiveness va	ries from good	I to poor, due to clagging with clay on many L	sile.
Observer not o	always motified	when inflow boxes are opened during bading	
		ed or protected species? YES NO	
Comments (details of t	turtle takes or whale	e sightings, dredged material, screening, biological by-catch, etc.):	
Dredged m	aterial is si	ilt and clay with some sound and couchel at	1011
Abiotic debris	includes: Shri	imp and fish nots, monofilarment; much bags wood,	M(,
Metal pipe, elect	trical wire, pl	clastic bags rubber floor mat, scrap metal, pla	Toke\
tencing, crab tra	p hat	or rad men, so of men, pe	Z)TC
<u>. </u>			
By- catch incl	1des: Rathery bi	onyozoa, Lightning whelk egg cases (Busycon	_
-gyracium)		the cases consider	_
There were	No incluent in	avaluina antectal et contra t	
	VICE PILO	Tvolving protected, threatened or endangered of	pewer
		Bridge Watch Summary	_
Species	# of Animals	Time / Location / Comments	
Tursiops truncatur	(o-8	0815/Sect. 6	
T+.	56	0928/end of jether	_
TE		1350 (and of settier (feeding	- ;
		The state of the s	_ ***
			-
bserver(s) on duty k	insten Dahlen 4	+ Brian Federto	

Dredge: FAGLE 1
Project: FREEPORT SUTRALLS CHANNEL

Date 28 / Ju	in / 01	Load Numbers 200 - 224
		-40% -4012 -90% -14012 -190 m 28-5511 95-16W
Weather Conditions (i	ncl. sea conditions) 9	Cloudy 5 10-15 BSS 2-3
Range of Water Temp	., Surface <u>28.5 - 35</u> °	C Below Mid-Depth 29.5-30°C
Condition and Effective	veness of Screening	iondition of screening is generally good. Screening
effectiveness varies	: And good to po	sor due to heavy day bading in some books.
Are there incidents in	volving endangered	l or protected species? YES NO
Comments (details of t	urtle takes or whale s	sightings, dredged material, screening, biological by-catch, etc.):
_		and crushed shell and day. Abiotic debris includes
golf ball fish and s	hrimp nets, more	filament stran and hooks, man bag, wood, lead weights
cloth, rope, scrap m	etal, etipine por	H3
By-coatch incl	uder feather b	mossa, Lightning whelks (Busycan contrarium)
Atlantic Hairy Tri	ton (Cymatium	pileare)
<u>'</u>		
There were	no incidents!	involving protected, the contened or endangered
species.		
		Bridge Watch Summary
Species	# of Animals	Time / Location / Comments
Tursiops truncatus	5-6	0930 Vertice
T-truncoas	4-8	
T. trincolus	5-10	1320 Festing at Jetties 1830 Reding @ Jetties
		122 Lecand a Tellier
Observer(s) on duty Ki	oten Darley o	and Brian Federko

Dredge: <u>Eagle 1</u>
Project: <u>Freepart Entrance Channel</u>, TX

WEEKLY SUMMARY

Dates 22 /July / 01 - 28 /July / 01 Load 1	Numbers 37 - 224	
D. CHI. T. C. C.	Mid-Depth 28-31F	
Areas Worked (lat/longs, stations) Oct. 2,3+6 Sta. Otto -40 to -40 to		28,22 N do-18
Are there incidents involving endangered or protected species?	YES	NO
Comments (turtle takes, whale sightings, effectiveness of screening, b	y-catch, material, other is	nfo):
Dredged material is silt, clay, sand and shell. A	thiotic debris indu	odes: shrippe nets
fish nets, line, monofilament, mesh bags, scrap metal, milk a	ente, crab traps plo	estic, cloth.
5 gallon buckers, rope, wood, plastic juice containers, st	reel cable, rug, soil,:	screen, rubber
floor mats, aluminum cans, fishing line, hooks and weig	hts plastic fencing	electrical wine
wire, hat, engine pans		
·		
By-catch includes: feathery byozoa, spot (Leiostomi	is kanathis unident	-Hed ects
Lightning whelks + egg cases (Busy can contrarium), A	Itlantic Hairy Triton (Emption pileare
Two Caretta caretta (laggerhead sea birtles) were	sighted from the	bridge one in
the channel, and one in the dump area.		
Produces with chagging continue in sections 2+6	where there are	longe amount
of clay. Boxes are often opened a chains book	ing reducing screen	in effectiverest
Chris Slay (Coastnise Consulting) and Rob Hauch (ACOE) were	both informed of	mablerer with
Screening loss.		
There were no incidents involving threatened protect	ettal as applaces.	snesies
Bridge Watch Summary	ar crawytre	A Contract of the Contract of
Date Various Species and Respective Number	Comments	
22 Your Tursions tuncour(324) Caretta caretta (1)	_	Section 2
23 July Teruncatur (25-36) (oreth carette (1) 24 July Teruncatur (7:10)		dump
25 Jucy Thruncatus (4-8)	Tt. 1130 - dump Tt 1230 - Reding at	
26 by thencen (6-9)	TE am-jetties	
29 / Duy T. truncatus (15-20) 28 / Duy T. truncatus (14-24)	The all day-jet	^
Observers on duty Kirsten Danlen and Brian Federica	allaby techning a	To a de Jennes
Observers on duty Kirsten Dahlen and Brian Fedorka		

Dredge: _____EAGLE | Project: FREEPORT, TX DAILY REPORT Date 29 | Tuly | 2001 | Load Numbers 225 - 248 Area(s) Worked Stations - 19000 to -14000 (Sec.6), and -4600 to 000 (Sec. 253) Weather Conditions (incl. sea conditions) Beaut Sea State 2-3; Winds 5 5-12; Clear > Partly Clouds all Range of Water Temp., Surface 29-30°C Below Mid-Depth 29-30°C Condition and Effectiveness of Screening Screening of stad inflow (mid) is essentially non-existent since the door won't stay closed during loading due to Faulty hydraulics. Condition of other inflow boxes is generally Are there incidents involving endangered or protected species? YES Comments (details of turtle takes or whale sightings, dredged material, screening, biological by-catch, etc.): * Screening effectiveness varies from fair to extremely pook. * Material continues to be a mix of silt and mud with varying amounts of sand (higher in section 3 and clay (higher in section a) * Abiotic debris included (2) Plastic Hill Crates (1) Bear Can, (1) Juice Can (1) Tox Truck, several mesh bags, plastic, rope, wire rope, monofilance line, wood, cloth, carpet, () golf ball (1) car bumper, and (8-10) pieces of ship net of varying size. * Biological by-catch included sargassum, bryozoa, whole and couste. shell, (1) Fish vertebrae, (1) Graff topsail Cattish (Bage marinus), (1) Suggest Mayor (Abustatul saxatilis), (WEel (Sp. undertified), and (1) Gulf Markacken (Brevoortin pate Bridge Watch Summary # of Animals Species Time / Location / Comments Tursions truncatus 11-15 0830 (First Sighting) - Sec. 3 - Feeding in channel Bottlerose Dolpha - seen throughout morning.

Observer(s) on duty KIRSTEN DAHLEN BRIAN FEDORKO

ENDANGERED SPECIES OBSERVER PROGRAM

Dredge: FAGLE / Project: FREEPORT, TX DAILY REPORT Load Numbers <u>249 - 271</u> 30 1 July 12001 Weather Conditions (incl. sea conditions) Sea State 2-5; What's a west of weather conditions Below Mid-Depth _29-30°C load to load depending on the clay content continues to consistantly be hydrause failure. NO YES Are there incidents involving endangered or protected species? Comments (details of turtle takes or whale sightings, dredged material, screening, biological by-catch, etc.): Dredged material continues to consist of silt, mud, clay, sand amounts of crushed shell. * Brotogical by-catch today included songassum, (1) Guger Alberto Corche undarpfied * Human generated waste included mesh bogs, plastic bags, (1) Rubber Tire, (-14) showp net remaints, (1) aluminum can rope (various lengths), carpet remnants, chain, and wads of monofilament line. sighted today. Bridge Watch Summary Time / Location / Comments # of Animals Species Throughout any in channel, beginning 0710 NES 1450 - 300 pt E of jetties; feeding T. truncatus Observer(s) on duty KIRSTEN DANCEN / BRAN FEDERO

ENDANGERED SPECIES OBSERVER PROGRAM

ENDANGERED SPECIES OBSERVER PROGRAM Dredge: EAGLE 1 Project: FREFPORT, TX DAILY REPORT Date 31 / July / 2001 Load Numbers 272 - 295 Area(s) Worked Sections 1,2, and 3 Weather Conditions (incl. sea conditions) Sea State: 2-3 All Day; Clear to Poloudy Stres; Winds 5-10 S Range of Water Temp., Surface 29°-31°C Below Mid-Depth 29°-31°C Condition and Effectiveness of Screening No change since 30 July 2001. Inthes boxes regularly close w/ clay and are opened mid-bad w/o being checked to the track vaciolent continues to be longed on observer load sho Are there incidents involving endangered or protected species? NO YES Comments (details of turtle takes or whale sightings, dredged material, screening, biological by-catch, etc.): * Stad mid inflow box continues to slip open during louding, thereby being poor for screening by coatch. * Material dredged continues to be a mixture of * Biological debris today included only sargassum * Trash today (mostly in diagheads) included: (~18) shump net

remnants, plastic sum gogales, ~12 ft of 1 m. wire rope, (8) mesh

produce bags, metal waste, wood, electrical wire, plastic Kieldie

pool, (1) rubber floor mat, bits of rope, fishing line, etch, plastic

Bridge Watch Summary

Time / Location / Comments

Species	# of Animals	Time / Location / Comments
tersiops truncatus	10-12	a.m. IN Chanel all morning First sighted & 0635.
T. francatus	6-12-	A.M IN Chanel all morning First sighted & 0635
Observer(s) on duty_	KIRSTEN)	DAHLEN BRIAN FEDERO

Dredge: EAGLE 1 Project: FREEPORT TX DAILY REPORT Date 01 | Aug | 2001 Load Numbers 296-318 Area(s) Worked Sections 2 \$3 : Stations - 90+00 to 0+00 Weather Conditions (incl. sea conditions) Sea State 2; and Clear, winds 5 5kts 1 p.m. Phydy Winds Range of Water Temp., Surface 29-30.5°C Below Mid-Depth 29-30.5°C Condition and Effectiveness of Screening Condition unchanged since 31 Toly 2001. Clagging continues to limit the ability to screen effectively due to the need to open inflow doors mid-load up checking for samples. Are there incidents involving endangered or protected species? YES Comments (details of turtle takes or whale sightings, dredged material, screening, biological by-catch, etc.): * Dredged material varies depending upon bottom depth and section - various mixes of clay, and, and sand * By-catch today included sargassum and (2) Fish: (1) Atlantic cutlassfish (Trickiums lepturus) and (1) Spot (Leiestomus xanthuius) Also observed in the clay were bivalves intentified as Southern Qualings (Mercenone compechensis) - numbering about 15-25 live \$ 12 she * Abiotic debris consisted of: (1) Mop Bucket (plantic), (1) boat soil, electrical wire, (8) shows not remnants, (1) whole shows not. (10) mesh produce bags, (2) metal crop traps rope, and fishing line. Bridge Watch Summary Time / Location / Comments # of Animals Species 0639-Bury 3 in changel Tursions truncatus 2 1047 that other, outside channel T. truncatus 8-10 1330 - ~1700 - Feeding Mak buoy 5. T. fruncatus Observer(s) on duty KIRSTEN DANCEN BRIAN FEDORED

ENDANGERED SPECIES OBSERVER PROGRAM

Dredge: <u>EAGLE 1</u>
Project: <u>FREEPORT</u>, TX

		DAILY REPORT
Date 02 1 ,	AUG 12001	Load Numbers 319 - 342
		3\$6 Winds Manable = 5-
Veather Conditions (i	ncl. sea conditions)	Sea State: 2 building to 4; Partly to Hostly Cloudy; Rain in a.
lange of Water Temp	., Surface	-30°C Below Mid-Depth 29.5-30°C
		Condition of screening unchanged since OIAva 2001.
Screenna effe	ctiveness conti	inves to be compromised by clogging problem
Faulty hydra	ulic doors, an	inves to be compromised by clogging problem and the 1ft x 3ft (approx.) hale in the bottom of
the port mid	box.	
are there incidents is	nvolving endangered	d or protected species? YES NO
Comments (details of	turtle takes or whale s	sightings, dredged material, screening, biological by-catch, etc.):
* One su	b-adult Logo	gerhead Sea Turtle was seen this afternoon
from to	he bridge	erhead Sea Turtle was seen this afternoon. - See Bridge Watch Summary below.
	đ	0
* Dredged	material con	stinues to be a mix of mud, sand, and clay.
* Biological	debris today	ncluded feathery bryozoa and sargassum.
* Abrotic des	bris included	(13) Shamp NET remaints, (9) mest produce
		wire rope, (1) 30 ft (approx.) length of
electrical	wire many	wads of monofilament line, (a) rubber floor
à	l various len	· / · · · · · · · · · · · · · · · · · ·
		0
		Bridge Watch Summary
Species	# of Animals	Time / Location / Comments
rsiges truncatus	6-10	1 Sighting ca. 0855. In channel throughout the day. Ford
eta caretta		1506 HRS- Near Broy 6. Surfaced for approx. 15-20 sec
		50 xels shoreward of broy. Swimming Southwar
	<i>-</i>	AHLEN BRIAN FEDORKO

Dredge: <u>EAGLE</u> |
Project: <u>FREEPORT</u>, TX

DAILY REPORT	
Date 03 AUG 2001 Load Numbers 343 - 3	66
Area(s) Worked Sections 2 \$3 mostly. Also sec.	(Load 344) F Soc. 4(Load 34-
Weather Conditions (incl. sea conditions) <u>Vanishe</u> - a.m. See State 34, close Range of Water Temp., Surface 29-30°C Below Mid-Depth	dr: umds to 15 Hs for clearing
Range of Water Temp., Surface 29°-30°C Below Mid-Depth	29°-30°C
Condition and Effectiveness of Screening Condition Slightly use	rse as Port Hid inflow
box door now slips open 6-12" during loading, Sim	ular to the ongoing
problem w/ the Stbol mid without box noted in	previous daily reports
Are there incidents involving endangered or protected species?	ES NO
Comments (details of turtle takes or whale sightings, dredged material, screening	g, biological by-catch, etc.):
* Specific clogging problems continue	to be noted on
instruction load sheets. Screening etter	tiveness continues
to vary from fair to poor depending a	your make-up of
to vary from fair to poor depending of diedged material and the physical tom box. Haterial diedged continues to var	dition of each inflow
box. Haterial dredged continues to va	<i>y.</i>
* By-catch included sargassum and (1) Great	Atlantic Cockle.
* Trash today included the usual shrimp	net remnants, metal
cash traps, monofilament line, scrap	metal, west produce
bags wood debris doth Habric, (1) beach	sandal (a plastic
mit jug, PVC Pipe, electrical wire, raingear Bridge Watch Summary	(1) plastic dall, and (1)
Bridge Watch Summary	(~/'xZ'x/')*
Species # of Animals Time / Location / Comments	
Ursisps truncatus 10-15 acts: 18 sighting @ 18	Light In Channel all a.
Birds:	<u> </u>
Frighte Birds 12 All day - over channe	<u>.l. </u>
Rosente Terrs 2 Load 359 - ca. 1530	
_	
Observer(s) on duty KRSTEN DANLEN BRIAN FETO	RKO

Dredge: <u>EAGLE 1</u>
Project: <u>FREEPORT, TX</u>

DAILY REPORT
Date 041 AUG 12001 Load Numbers 367 - 391
Area(s) Worked Sections 1, 2, 3, 4 (partial), 6
Weather Conditions (incl. sea conditions) Sea State - 2 (a.m.); 1 (p.m.) Winds 1-5 NEE. Hazy
Range of Water Temp., Surface <u>19'-30.5°C</u> Below Mid-Depth <u>19'-30.5°C</u>
Condition and Effectiveness of Screening Condition and effectiveness unchanged
since 03 Aug 2001. Unable to check for turtle take in dragheads
loads 376 and 385 as dragarms were not brought on deck between loads.
Joads.
Are there incidents involving endangered or protected species? YES NO
Comments (details of turtle takes or whale sightings, dredged material, screening, biological by-catch, etc.):
* Material dredged continues to vary between loads. Material
* Material dredged continues to vary between loads. Material consists of various amounts of clay, sitt, mud, and sand
* Biological debris today consisted of sargassum, feathery bryazoa, Swithern Ovahogs (Mercenania campechiensis), and (1) Gulf Menhaden (Brevaertia petronus)
bry 2000, Southern Ovahogs (Mercenaria campechiensis), and
(1) Gulf Menhaden (Brevaartia petronus)
* Abrolic debiis included (21) Shump net remnants, (4) mesh produce
bags, (1) plastic basket, (1) battery, (1) hardhat, (2) carpet remnants,
bags, (1) plastic basket, (1) battery, (1) hardhat, (2) carpet remnants, (1) pro pipe, (4) wire rope-10ft, 5ft, 10ft and 1 unknown length, various
(1) plastic salt bag. (1) plastic gatorade bottle, metal waste, (1) plastic toy. Bridge Watch Summary
(1) plastic salt bag. (1) plastic gatorade bottle metal waste, (1) plastic toy.
Bridge Watch Summary
Species # of Animals Time / Location / Comments
Tursings francatus 3-4 1040 NRS - Sec. 3 - in channel afternoon.
T. truncatus 15-25 1200 Nes-Feeding in channel Some bow-viding Cosmo
Torsizes francatus 3-4 1040 NRS - Sec. 3 - in channel. Throughout afternoon. To truncatus 15-25 1200 NRS - Feeding in channel. Some bow-riding Casmo boat. Birds: T. truncatus 10-20 1930 NRS - Bow-riding "Surfside Princess" Casmo boat.
Frigata magnificers 17 1350 NRS - Frigate Bird
Observer(s) on duty KIRSTEN PAHLEN BRIAN FETORKO

Project: FREEPORT ENTRANCE ChanNEL, TX

Dredge: EAGLE /

WEEKLY SUMMARY (Page 1 of 2 This week) Dates 29 / July / 2001 - 04/ Aug / 2001 Load Numbers 225 - 39/ Range of Water Temp., Surface 29°-31°C Below Mid-Depth 29'-31'C Areas Worked (lat/longs, stations) Sections 1,2,3,4 (to about station +2+00), and 6 Are there incidents involving endangered or protected species? YES Comments (turtle takes, whale sightings, effectiveness of screening, by-catch, material, other info): * (1) Loggerhead Sea Turtle was sighted from the bridge on 2 Mug No interaction w/ dredge operation was observed - see Bridge Watch Summery. * Material varies depending upon section dredged. In general, sections I and to have high amounts of clay as do the deeper portions of sections 2 and 3. Less day and higher sand and mud content is generally seen in most of sections 2 and 3. * Problems ut screening condition include the approximately 1ft x 3ft hole in the bottom of the Port Mid inflow box. This hole has compromised screening effectiveness for loads 1-391 thus far Anticipated State of repair is unknown. Observer KIRSTEN DAHLEN reminded Project Mage. Pedro Genzalez of this situation on 02 Aug. & NOTE - CAPTAIN BABB WAS NOTIFIED OF THIS Bridge Watch Summary CONDITION GAUG. 01 - WHEN THIS REPORT Date Various Species and Respective Number Comments Tursiops truncatus: #11-15 29 / July Botherose Dolphin are generally T. fruncatus: # 18-27 30/ July seel each day in and around # 16-24 the channel Behaviors observed 31 / July include feeding and bow-riding # 20-25 01 AUG T.t.: #6-10 02 / AUG : Caretta caretta: #1 various vessels bow waves. T.t.: #10-15 03 / AUG Individuals include both T.t.: #28-49 04 / AUG adults and juveniles. Observers on duty KIRSTEN PAHLEN BRIAN FEDORKO

Project: FREEPORT ENTRANCE CHANNEL, TX WEEKLY SUMMARY (Page 2 of 3 This Week) Load Numbers <u>225 - 39</u>/ Range of Water Temp., Surface _____ Below Mid-Depth — Areas Worked (lat/longs, stations) See Page 1 of 3 Are there incidents involving endangered or protected species? YES Comments (turtle takes, whale sightings, effectiveness of screening, by-catch, material, other info): * Problems w/ screening condition also include the failure of the hydraulic rams on the Port Mid and Stad Mid inflow boxes to effectively and consistantly keep the boxes absed during loading This condition problem on the Port Mid box developed this week while the Stood MID box has been a problem since last week. Capt. Babb states that new rams are currently on order. * High clay content continues to affect screening effectiveness as inflow boxes need to be opened mid-load to flush out clay and thus any biological samples that may be in the boxes. Little or no screening occurred during 62 of 167 loads this week dire to inflow boxes clogging w/ clay. (Not including lack of screening due to the Stbd. Mid box being open 12-24 inches every load due to problem described above. Bridge Watch Summary Date Various Species and Respective Number Comments Observers on duty KIRSTEN DAHLEN BRIAN FEDORKO

ENDANGERED SPECIES OBSERVER PROGRAM

Dredge: EAGLE /

WEEKLY SUMMARY (Page 3 of 3 THIS WEEK)

	9 JULY 2001 - 04 AUG 2		ımbers <u>225</u> -	
	ater Temp., Surface		id-Depth	
Areas Work	ed (lat/longs, stations) <u>See Pag</u>	e 1 of 3		
Are there in	ncidents involving endangered or pro	otected species?	YES	NO
Comments (turtle takes, whale sightings, effectiver	ness of screening, by-	-catch, material, o	other info):
* Bi	plogical "catch" consisted	l of: Sarge	ssum; Feat	hery Bryozoa;
	Southern Qualogs (2. shells			
	Brevoortia petronus); ()		_	
	Sergeant Major (Abudeted			
_	Trichinous lepturus); (1) Sp			
(2)	Giant Atlantic Cockle (De	nocardium robus	tum). The	eels are general
seen	in the hopper; other fish	are generally	recovered	
dro	raheads and spill deck	. Also (1) fis	L vertebrae.	**
	Q			
* Abic	otic debris totals for	the week	include: 9	5 (approx.) Shring
net	remnants; (~42) mesh p	roduce/onion b	mas ; (~7)/	engths of wire rog
	tless wads of fishing he		1 1	1 1
	s, metal debiis, plastic			
	trical wire, metal crab			
rope	, and other misc. tra	sh (see each	daily repo	rt for specifics.
·		Watch Summary	, ,	
Date	Various Species and Respective Nu	mber	Comments	
/				
/				
/				
/				
/				

Dredge: Eagle One

Project: Freeport Entrance Channel, TX DAILY REPORT / Aug / 2001 Load Numbers 392 - 414 Area(s) Worked Sect, 1,2,3,6 Sta -46th to +2th; -140th to -90th; -190th -140th 28°55N 95°16W Weather Conditions (incl. sea conditions) P. Cloudy /hazy, am rain, winds It + variable, BSS 1-Range of Water Temp., Surface 285 - 30.5°C Below Mid-Depth 28.5 - 30.5°C Condition and Effectiveness of Screening Effectiveness ranges from fair to virtually non-existent. Approx. 1'x3' hade remains in part mid box. Hydraulic problems cause part (6") mid has inflow doors to open during landing. Boxes often opened during landing without notifying observer on bridge worted, leaving to wiknown degree of sereening loss, in addition to the above mentioned sources of screening loss.

Are there incidents involving endangered or protected species?

YES

NO Comments (details of turtle takes or whale sightings, dredged material, screening, biological by-catch, etc.): Vredged material is mainly silt + clay with some sand + crushed shell. Amount of clay increases as depth increases in sections 2+3; sections 1+6 are mainly clay. Boxes opened in all sections due to problems with clay, and other concerns, -further reducing screening for biological sampler boxes opened when "clogged" By-catch includes: bryozoa, sargassum, whelk egg cases (Busycon contrarium Gulf Menhaden (Brevoortia patronus Dragheods not checked on boad 407, as dragarms not brought on board. Debris includes: wood pieces (2), bits of rope + line 6 25' (6) Ziploc bags, whole shrimp nets (2) pieces of shrimp net (12), scrap metal, metal engine parts, metal pipe, aluminum cans, golf balls, plastic garment bag, rocks swim flippers (1) mush bags (15), lead fish weights (3), baseball cap (1), wads of manufilament (18), tire (1), fish net pieces (1) Bridge Watch Summary # of Animals Time / Location / Comments Species 0645 - buoy 5 lursiops truncatus 1300 - all afternoon-feeding in channel + T. truncotus 10-20 bouriting

Observer(s) on duty Kirsten Dahlen + Brian Fedorko

Dredge: <u>Eagle 1</u>
Project: <u>Freeport Sontrance Channel</u>, TX

Date 06 / 40	6 / 2001	Load Numbers 415-4	1 0	
Area(s) Worked Sect. 1	3,6,25ta -46to	0to; -190to to -90tos	Z8°55N 95°16W	
			10; P.cloudy, H. air, BSS 1	
	·	Below Mid-D		_
Condition and Effectives	ness of Screening Por	ary stb mid inflow	paxes continue to open during loo	ding du
			t mid inflow will be fixed soon. &	
			generally fair due to cla	
Are there incidents inv	olving endangered o	r protected species?	YES	
Comments (details of tu	rtle takes or whale sig	htings, dredged material, sc	reening, biological by-catch, etc.):	
Dredged monterio	l is clay and silt	, with some sand + cri	ushed shell, Material is mostly o	<u>clay</u> ir
			times. Captain Bobb reports that	
	-		ng and to the hydraulics on	
mid doors Draghead	s not brought abo	we the waterline of	on load 439	
Biological by-c	atch includes: Sar	gassum, feathery bryozoa	, colonial hydroids (un id: 1), Ligh	thing.
Whelk egg cases CBU	sycon contrarium),	sea whip Cleptogorgia	Virgulata), unidentified ects of	<u>7 i</u> sc
clams (Dosinia +	•			
		pieces, (13) pieces d	rope, Sail fragment, shirt, 20	<u>2'</u> steel
			of monofilament, 40' of 2"Cd	
			allon bucket, toy Tonka Truck	
plastic bottler, garbage				
, , ,	<i>J</i> ,			
	<u> </u>	Bridge Watch Summary		
Species	# of Animals	Time / Location / Comm	nents	
Tursiops truncatus	6-10-3-4	0634 - channel in	section 6 - Porpoising	
T. truncatus	6-10	in channel - 0720	· inchannel all am.	
T. truncatus	9-12	1040 - between dury	2 and &ct. 1	
T. truncatus	10-15		nd of jetlies - all afternoon	
T. truncation	4-6	1500- Section 1	J	
Observer(s) on duty	irsten Dahlen	+ Brian Fedorko		

Dredge: <u>Eagle One</u> Project: <u>Freeport Entrance</u> Channel, TX

Date 07 / AUG	/ 2001	Load Numbers 441 -471
		-85; -40th 0; 0th +60th 28.55 N 95.16 W
		dy, pm light rain; winds + => 5 5-10; 1355 1-3
		Below Mid-Depth 30-31°C
		iveness continues to vary depending on material being dredged,
		e to slip open the to hydraulic problems. Repairs completed
		made to mid inflaw hydraulics when parts arrive.
Are there incidents invol	lying endangered or p	protected species? YES NO
Comments (details of turt)	le takes or whale sight	ings, dredged material, screening, biological by-catch, etc.):
A juvenile Chelo	nia mydas mydas	(green sea turtle) was observed from the dredge between
		ised Lepidochelys Kempii (Kemps Ridley) was observed by
		ne Freepart jetties. The dredge had no appearent
interaction with either	er turtle. Please se	e bridge wortch summary.
Dredged mater	ial is silt and d	ay, with some sand + enished shell in section 3. Boxes
continue to be occasiona	tly clagged with	day, and are opened refter notifying observer.
Biological by-cat	ch includes: Songa	rum, bryosaa, Gulf Menhaden (Breusortia patrones),
DIE clam (Dosinia	= discus)	
Debris includes: me	ital tank, 5 gallon	bucket, engine, random plastic, (1) mesh bags, 129 shrimp
net pieces (18) bits e	of rape, (13) wods	of monofilament, (2) lengths of wire rope, conside
cable, salt bags cloth,	scrap metal, fish h	ooks lead weights racks, wood, duct tape
		1 After loads 469, 454, 449
	Brie	dge Watch Summary
Species	# of Animals	Time / Location / Comments
Tursiops truncatus	5-10	1310 Sections 1+6/Feeding
Chelonia mydrs mydrs	2 juvenile	1350 / en route to dig one # I / surfaced headed west
T. truncatus	10-15	1645 / entrance to jetties / feeding
Lepidochelys Kempii	1, adult-sized	1730 / Way 5 & facing WSW, but not really moving. "a words right front flipper a few times.
Observer(s) on duty χ	irsten Dohlen	and Brian Fedorko

	Dredge: <u>Ea</u>	gle One
	Project: Free	port Entrance Channel, TX
		DAILY REPORT
Date D8 / A	UG / 2001	Load Numbers 472 - 503
		to 90to40to 0to, 28.55 N 95.16 M
	•	Cloor => PCloudy winds 5 5-10 => WSW 10-15; BSS 2-3, pm shower
		C- 31.0°C Below Mid-Depth 29.5°C - 31.0°C
Condition and Effectiv	eness of Screening	fectiveness varies from fair to poor depending on amount of
clay in load Port +	SIB MID boxes co	rance topen 12-24" during loading due to problems with
hydraulics. Stb M has likely been th	10 inflow "floor" sucre longer.	screening has 1.5 'x1' hale observed in bood #487, Hough
		or protected species? YES NO
Comments (details of t	urtle takes or whale s	ightings, dredged material, screening, biological by-catch, etc.):
Dredged materia	d is sitt and cla	y with small amounts of sort and croshed shell. Boxes
• • • • • • • • • • • • • • • • • • •		airs have been completed to railing on part aft inflow
box. Dragheads	were not checke	1 offer bod 481 as dragarms not brought on
board		
Biological by-c	otch includes: Sar	gassum, bryozoa, eels (2), Great Atlantic Cockle (Dinocardium
cobusum), polychaet	es (unidid), sout	hen Ovohog (Mercenoria compechiersir) Atlantic
attassish (Trie)	nivrus lepturus)	
Debris includes:	44) lengths of ro	pc (2-35'), (26) shrimp net pieces, UF) mesh bags, (29) wad
		ite rope, swim mask, bungee conds, golf balk, wood, scra
metal, fish nets, g	Il net (5' piece), s	all bags, plastic jug, parts, 20' wire rope, old rope hand
made fishing net		
		Bridge Watch Summary
Species	# of Animals	Time / Location / Comments
Tursiops truncatus	3-4	0920 - Section 1
T-truncatus	5-6	1150 - buoy 3 - larger, several we chunks out of dorsal fir
T. truncatus	2.3	1310 - dump feeding + toil slapping; one juvenile all across channel in groups of 3-6,
T. truncation	16.20	1325-2000 Sect 1-feeding, porpoising + tracing
Observer(s) on duty	Kinsten Dohlen	and Brian Fedorko

Dredge: <u>Eagle</u> One Project: <u>Freeport Entrance</u> Channel, TX

Date 09 / AUG / 2001 Load Numbers 504 - 532	
Area(s) Worked Sect. 13 4 Sta-140 to -90to -40 to 0 to 60th 28.55 N 95.16 k)
Weather Conditions (incl. sea conditions) M. Cloar >> Cloub, wind 5w 10-12; BSS-2=	>2
Range of Water Temp., Surface 29.6-3/°C Below Mid-Depth 29.6-3/°C	
Condition and Effectiveness of Screening Effectiveness varies from Pair to poor depending on m	atecial
being dredged. Stor Port mid continue to open 12-24" during looding. 1.5' x 1' hale	in floor
of other inflam futher comprended streening effectionness	
Are there incidents involving endangered or protected species?	
Comments (details of turtle takes or whale sightings, dredged material, screening, biological by-catch,	etc.):
Dredged material is sitt and clay with some sand and enisted shull. Boxes car	where to
clog often with clay and are opened after notifying observer.	
Biological by-catch includes: unidentified exis sorganium, byozoo, stone or	mbs
(Menippe mercenaria)	
Debris includes: (12) mesh bogs (8") shring nets, (12) monoflament, (12) cis	abe wire rob
plastic has extragion cords electrical wire tire, 5 gallon buckets plastic debris	With the second
cable salt bros love Ashine like is neared lacery to know (300 t text with	hoor sund A
troy of charge soltimes, cloth, 40' line (3"d'onceter), pus pipe	
2 frigate brids (Frigata magnificens) were sighted. No sea turtles were obser	red today.
Bridge Watch Summary	
Species # of Animals Time / Location / Comments	
Tursiage truncatus 4-8 0718-bary 3- all am	
T truncator 10-15 1155 dump-feeding	
T. truncatus 8-12 1210-] effect- Reding + acrobates	
T. truncotus 10-15 Sections 1+6; 1300-1 2000; feeding	+ playing
Observer(s) on duty Kirsten Dotilen and Brian Federko	

Dredge: <u>Eagle</u> One Project: Freeport Entrance Channel, TX DAILY REPORT ate 10 / AUG / 2001 Load Numbers 533 - 553 rea(s) Worked Sect. 1,3,4,6 StA - 140th -90th; -10th +60th -190th -190th -19428 55 N 95 16 W 'eather Conditions (incl. sea conditions) P-Cloudy \$ 10-15-3 5-10; BSS 2-3) 2-3 Swell ange of Water Temp., Surface 30°C-31.5°C Below Mid-Depth 30°C-31.5°C ondition and Effectiveness of Screening Effectiveness continues to vary from fair to poor depending I material being dudged. Part and STB Mid inflaw choors continue to open during loading we to problems with hydraulies. There is a 1.5' x1' hole in screening of 578 mil in flow. re there incidents involving endangered or protected species? NO YES omments (details of turtle takes or whale sightings, dredged material, screening, biological by-catch, etc.): Dredged material in sections 3 and 4 is thick silt and clay with some sand ad cousted shell. Material in section 1 is largely day, with some silt, leading to agging of inflaw boxes during landing. At times (see boads 517 and 533), "chagging" pears to be attributable to high water level in the happer as opposed to actual clagging th day and Lebris. Observer not always notified when inflow boxes are opened. Biological by-cotchincludes: (3) unided eels, sargassum, bryozoa, moon snail (a.Ka. Mark eyer & Polinices duplicatus) Tragheads were not inspected after load. #549 as they were not brought on board Debris includes: 100'+ rubber hose, plastic milk jug, rug, lead flahing weights, salt ngs, garbage bags, pue pipe, cartire, 30' plants conted wire rape, several large, rocks and, (28) water of marallament, (12) therether of rope, (17) meshbage, ziplaces beach raing (2) (5) string nox pieces, 1 pr-of pants, matertage Bridge Watch Summary ecies # of Animals Time / Location / Comments rsiops truncatus 5-6 0915-1200/BUOY5 truncatus 16170 1210-5 2000 - Feeding between jetties & buy 8 igata magnificens 2 of 1200-1600- over jettees

exer(s) on duty Kinsten Dohlen and Brian Fedorko

ENDANGERED SPECIES OBSERVER PROGRAM

Project: Freeport Entrance Channel, TX

DALL CONTRACTOR
Load Numbers 554 - 575
16 11 / AUG / 2001 Load Numbers 554 - 575 To and Numbers 554 - 575 To and Numbers 190 to 19
16 1/ AUG /2001 Load Numbers 55 N 95.16 W 12(5) Worked Sect. 1.3.4 6 Sta - 140 1 - 90 1 - 10 1 + 60 1 - 190 1 - 146 28.55 N 95.16 W 22(5) Worked Sect. 1.3.4 6 Sta - 140 1 - 90 1 - 10 1 + 60 1 - 190 1 - 146 28.55 N 95.16 W 22(5) Worked Sect. 1.3.4 6 Sta - 140 1 - 90 1 - 10 1 - 10 1 - 190 1 - 146 28.55 N 95.16 W 23(5) Worked Sect. 1.3.4 6 Sta - 140 1 - 90 1 - 10
eather Conditions (incl. sea conditions) 9. Cloudy 3 Clean : 3W 3 Touch 39.5°C - 31.5°C
eather Conditions (incl. sea conditions) Y. Claudy & Clean, Below Mid-Depth 29.5°C - 31.5°C mge of Water Temp., Surface 29.5°C - 31.5°C Below Mid-Depth 29.5°C - 31.5°C mge of Water Temp., Surface 29.5°C - 31.5°C Below Mid-Depth 29.5°C - 31.5°C mge of Water Temp., Surface 29.5°C mge of Water Temp., Surface 29.5°
inge of Water Temp., Surface 29.5°C - 31.5°C Below White Depth 2011. Indicion and Effectiveness of Screening Effectiveness varies from fair to poor depending on material being dug. Approx.
is inflow boxes continue to open a
5'x1 hale remains in 5th mid inflow floor screening.
\sim
is sidents involving endangered or protected species?
tale sightings dredged material, screening, biological by-catch, etc.).
Tradged moderial is silk clay sand the star mid box chained shut after boad + 568 as
tradged moderial is silt clay, sand and chand street, book shared that after land 568 or
andravice ram wild has broken lave
Biological by - catch includes: Sargassum, bryoson, Lightness, Lightness,
Giant Atlantic Cockle (Dinocordiva robustine)
16) I pieces of pus Piec
Trobris Includes: (12) much bags (10) shring news (5) lengths of rape; (3) pieces of pus piece. Trobris Includes: (12) much bags (10) shring news (5) lengths of rape; (3) pieces of pus piece.
Txbris Includes: (12) much bags (10) shrimg new of tender plants, 25' shair stray steel, (17) wads of monoflament (12) lead weights wood fabric shackle, plants, 25' shair stray steel,
plastic strat shoe lace, plastic juice containes
plastic star, star was for
Bridge Watch Summary
- // comments
Species # of Animals Time / Location / Comments 4 0745 - near jettics - all ara-
The Australian -
I tracours 3-4 0912 - Near Dray 3 - we per
I transcours 5-12 1200 - feeding inside jetties who part to the pair
T truncated 6.12 1200 - teraing matter includer mother least pair
1,470
Observer(s) on duty Kinsten Dohlen and Brian Fedorko

Dredge: <u>Eagle One</u>
Project: <u>Freegort Entrance Channel</u>, TX

WEEKLY SUMMARY

Dates 05 / Aug / 2001 - 11 / Aug / 2001 Load Number	ers 392-575 p.1.682
	•
	epth 28.5 ~ 31.5°C
Areas Worked (lat/longs, stations) Sect. 1, 2, 3, 4, 6 Star - 190th to - 40th - 10th + 1	60 too, 28.55 N 95.16 M
Are there incidents involving endangered or protected species?	YES NO
Comments (turtle takes, whale sightings, effectiveness of screening, by-cate	ch, material, other info):
Two turtles were sighted from the bridge on Of August. Ajuve	mile Chelonia mydas mydas (Green)
surfaced outside the dumpsite hooded West. An adult-size Lepidochel	\
observed by K.D. and make Josh Lynch near buoy #5 Neither	turtle appeared to have any
interaction with the dredge.	
Repairs were completed to the 1'x3' hale in part mid int	Town screening during boat #454
on 07 August (first noticed and reported to couprain and project	marager 20 July, after load # 6).
Bopairs were completed to part aft infland railings during boo	6 # 484-486 as 08 August. A
1.5' X1' hole was noted in the Stb ruid inflow screening af	0
and STV mid inflow duors continue to open 6-24" durin	
hydraulics, repairs will be made when parts arrivelon orde	c since dry dock) STB MID chained \$ 568.
Dredged material in sections 3+4 is clay, silt, sand and	orushed shell. Aside from
problems with mid inflow door hydroulies, screening is generally	good in these sections.
Material in sections 1,2+6 is largely day and 5:1+, Be	exps clap often in these areas
and are opened and cleaned often - Problems with clay b	lockage resulted in poor to
non-existent screening in 68 loads this week. Dragheow	is were not inspected after loads
Bridge Watch Summary	
Date Various Species and Respective Number	Comments
07 / Aus C. mydas mydas (1 javenile)	surfaced outside dump, headed west.
	oury 5; "waved right trave flepper several
	times, taking WSW topping, bow-riding t
CL AUG T. truncado (32-47)	freding throughout area.
Of ALG T. Annewers (5-25)	
08 / AUG T. + MUNICALUS (26-33)	
Observers on duty Kirsten Dohlen + Brian Fodorko	

Project: Freegore Some Channel TX

WEEKLY SUMMARY

Dates 05 / Aug / 2001 - 11 / Aug / 2001 Load Numbers p. 2 of 2	
Range of Water Temp., Surface Below Mid-Depth	
Areas Worked (lat/longs, stations)	
Are there incidents involving endangered or protected species? YES NO	
Comments (turtle takes, whale sightings, effectiveness of screening, by-catch, material, other info):	
407, 439, 449, 464, 481 as dragarms were not brought on board	
Biological bycatch includes: bryozoa, sargassum, whelk egg cases (Busycan contracion)	,
Gul Manhadea (Braigertia patronus), Sea While (Leptogergia vigulates), Disc clams	
(- 1) d'ans colonial hydraids (unid-1) eels (unid-1) polychartes + tube worms (un id	, (L.
Court Allandie Carkle (Dinocordium robustum), Southern Quahay (Mercenaria compechic	(L(,L)
Attantic Cutton Ash (Trichiums leptons), Stone Crob (Menippe mercenaria), Shork Eye (Polinices objet	i'cat
Debris includes: (100) shrimp net fragments, (2) whole string nets, (34) short (612) lengths of	ope,
(01) was be (129) was of manefilament (6) pieces of wire rape 10-40, courties pros	· wy
cloth sharkles random postic lead Ashing weight 25 chain, plashe strap, scrap mer	w.
shoe lace, plastic drink containers engine parts obscuirum cons golf balls baseball cap (4) tires	yell
net pieces, sail fragments, shirts 20' steel bar, anchor chain & shaft, electrical cable, 40' mo	oring
Line, 5 gallon buckers Tanka truck 20' rubber hore, co-axial cable, salt bags fish hooks swipe neask	1 685
his too hunger sords parts (2) extension cost 300' rope like Wrignastaniant chanks every	3
duce trace bungee cords parts (2) extension cord, 300' rope line Wreanasteneum chanks every rug, 100' rubber ham, (2) beach chairs Bridge Watch Summary	
Date Various Species and Respective Number Comments	
09/AUG THUREATUS (32:50); Frigoto Magnificens (29)	
10 / AUG T. truncatus (21.26); F. magnificas (2%)	
11 / AUG T. + runcoaus (A-32); F. magnifleur (2°+)	
Observers on duty Kirsten Johlen + Brian Fodorko	

Project: Freeport Entrance Channel,

Dredge: <u>Eagle</u> One

DAILY REPORT (Page 1 of 2) Date 12 | AUG | 2001 Load Numbers 576-597 Area(s) Worked Sect. 4/3; 1/6 StA. -10+00 to +50+00; -90+00 to -190+00 28.55 N 95.16 W to 10kts; CleAR Sties (Partly Cloudy late p. Weather Conditions (incl. sea conditions) Beauf. #2 \$3 Range of Water Temp., Surface 30-31°C Condition and Effectiveness of Screening A combination of factors continue to eliminate be the single largest contributor Are there incidents involving endangered or protected species? YES Comments (details of turtle takes or whale sightings, dredged material, screening, biological by-catch, etc.): (cont'd) to the problem. However, the frequency at which inflow boxes are opened mid-load by the dragtender continues directly to which shift (0530-1130 vs. 1130-1130) is dredging. Observers continue note all times when inflow boxes are opened to thoroughly check for turtle takes. The box is to be repaired on 13 Aug. The on the stood mid box was removed today. This the door swings freely and box. The port though the screen door opens up to 24" during its broken hydraula ram. It is in this box will continue Bridge Watch Summary Time / Location / Comments Species # of Animals Dolphus continue to Frequent both the disposal Tursiops truncatus 19-29 (groups of 2 to 18 - # could be area and channel from 1st light (~0640) to last higher - difficult to know if individuals get counted twice throughout the day.) Kinsten Dohlen and Brian Fedorko

Dredge: <u>Eagle One</u>
Project: <u>Freeport Entrance</u> Channel, TX

Date 12 1	AUG / 2001	Load 1	Numbers	Page 2	of Z			
Area(s) Worked Se	ec. St	<u> </u>		<u> </u>	28.22 N 92.19 M			
Weather Condition	s (incl. sea conditio	ns)						
Range of Water Temp., SurfaceBelow Mid-Depth								
Condition and Effe	ectiveness of Screen	ng						
Are there incident	ts involving endan	gered or protect	ted species?	YES	NO			
Comments (details	of turtle takes or w	nale sightings, d	redged materia	l, screening, b	iological by-catch, etc.):			
(cont'd) rex	airs are mo	de to th	he hydrau	lic ram.	. The only inflow			
box that	consistantly	produce	es effect	five scre	ening is the			
		/			makes a big			
enough me	ess on the	nearby	catwalk	to nec	essitate opening			
	_	,			is likely due			
					raches this box			
					dragheads continue			
					o "wash" them befor			
					This activity may			
further re	educe obse	rvers'abilit	go to a	letect a	turtle take.			
			/					
X Burlogical	and abiotic	debois co	ntinues to	be the	some assortment as			
O'CO			atch Summary		3 w			
Species	# of Anima		/ Location / Co	omments				
	,, e 	_						
								
Observer(s) on du	ty Kinsten De	hlen and	Brian For	Horko				

Dredge: <u>Eagle One</u>
Project: <u>Freeport Entrance</u> Channel, TX

Date 13 / AUG / 2001 Load Numbers 598 - 619
Area(s) Worked Sect. 3 \$ 4 Sta - 10+00 to +50+00 [2 loads in 6 78:55 N 95:16 W
Weather Conditions (incl. sea conditions) Beaufort # a.m.: 3; p.m.: 2 / Mostly Cloudy all Day; Winds S p.m.
Range of Water Temp., Surface 29.5°-30.0°C Below Mid-Depth 29.5-30.0°C
Condition and Effectiveness of Screening - Unchanged since 12 Aug 01 w/ the exception
of the hidauli care on the Box Ma will him the 1225 year to be the
ram snapped off & the mount bolted to the top of the box. Screen door is not inoperable.
Are there incidents involving endangered or protected species? YES NO
Comments (details of turtle takes or whale sightings, dredged material, screening, biological by-catch, etc.):
* Beginning w/ load 620 on 14AUG, Inflow through Port Mid box will
not be screened since the door swings open freely during loading
Flow cannot be diverted to Aft box dire to a broken chain
(broken since 19 July 01) on the hatch that stops flow from the main pipe to the
(mul box. This situation will be updated in tomorrow's DAILY REPORT.
* Dredged muterial continues to be a mix of mud, clay, sand, & shell do
* Biological debris included: (1) Unidentified Crab (in hopper), (1) Mullet (on
spill deck under draghed), (1) Eel (in hopper), sorgassum, bryozoa, and
* Abotic debris included: (8) Shring Net remnants, (1) Steel Trailer frame us/ rubbe
tire, carpet, (2) Mesh produce bags, (1) PlAstic Milk Crate, (2) PlAstic Soft Boys, (1) cartire
electrical wire, (1) PVC Pipe, 15 ft wire Rope; several la rocks, lots of fishing gear was
Bridge water Summary
Species # of Animals Time / Location / Comments
Tursiops truncatus 10-18 0640-2020- In and around channel throughout
the day. Near jetties and further offshore (Bury)
No Turtle Sightings Today.
Observer(s) on duty Kinsten Dohlen and Brian Fedorko

Dredge: <u>Eagle One</u> Project: <u>Freeport Entrance</u> Channel, TX

)ate 141 AUG 12001 Load Numbers 620 - 641
Jea(s) Worked Sect. 3#4 STA -10+00 to -+50+00 /+2/och Sec 6 28.55 N 95.16 W
Veather Conditions (incl. sea conditions) Beauf. # 2. all day; an Cloudy of course of the Charma of Lt. Winn
lange of Water Temp., Surface 29.5-310°C Below Mid-Depth 29.5-31°C
Condition and Effectiveness of Screening Hydraulic Rags for both mid boxes did not
serve today Loads 620-626 were completed w/ no screening of the
Part Mid box as the door swings open freely during loading and flow
Are there incidents involving endangered or protected species? YES NO
Comments (details of turtle takes or whale sightings, dredged material, screening, biological by-catch, etc.):
was not diverted to the aft box due to the broken chain on
the hatch floor that stops flow to the mid box from the man pipe.
It 0630 NRS, the crew respond the hydraulic ram from the port and
box and repaired the broken chain to stop flow to this box.
Hydraule Rams are expected to acrive sometime 15 AUGOI. Some
material continues to Flow through the Port Mid box Loads 627-641
were completed using the 2 Att boxes only, causing a higher
frequency of closura for some loads, creating a need to
open the boxes mid-load w/o being thoroughly cherted for turil
- It I have some anount of clay arong business
1) Tolles were souted today I Other screening conditions same as noted to is no
Biological & Abiotic debis similar to previous days. (Specifics on back at august
Biological & Abiotic debis similar to previous days. (Specifics on back of augmal) Bridge Watch Summary
Species # of Animals Time / Location / Comments
Tursiops truncatus 12-22 Lute a.m E. 1-2020 HES (last light) - Observed both
uside & outside the atties in 2 groups of
10-12 each Feeding and playing"
Observer(s) on duty Kinsten Dohlen and Brian Fedorko
Observed(2) on anti-1/11/24/11 Novement

Dredge: <u>Eagle One</u> Project: <u>Freeport Entrance</u> Channel, TX

Date	/ 2001	Load Numbers	642-6	663	
uea(s) Worked Sect. 3					75°16 W
Weather Conditions (incl.	sea conditions) Beau	uf. #1-2 a.m.; 2-	3 p.m. ; Most	x to Partly Cloudy	All Tay Winds p.m. 10-15
Range of Water Temp., Su			•	, ,	• /
Condition and Effectivene	ess of Screening Zac	I mid inflow.	box m u	se again a	as of load
558. Hydraulic			_	1 1	^
sexice. High day					
Are there incidents invo	lving endangered or	protected species?	YE	cs C	NO
Comments (details of turt	le takes or whale sight	ings, dredged mate	erial, screening	g, biological by-	-catch, etc.):
* Do turtles u	vere sighted	today.			
Haterial consis	Is of a mix	of mud, sil	4, sand,	lay, and	shell debris.
As section 9	I is getting a	Leeper, the	amoun	7 of lang	ge clay
chunks appe	ears to be	Increasing	- conta	buting to	dogging
of inflow.	screening.) 	<u> </u>	
& Brologial		included! a	usters: s	hump (1);	Dinocardium
robustum (1)-					
(Brevootha par	`		- ()	,	
· Abrotic debii					
(1) 10ft x 1/2 m. ; (1)					
(1) 10 ft piece of				•	-
Ine w/ hooks \$					
		dge Watch Summa	,	doth.	
Species	# of Animals	Time / Location /			
Tursiops Livicativs				Asile chan	al; Tight group.
Tursings frumates	12-20	Throughout.	Day- insid	le \$ outside	Jethes- Feeding
		_			
Observer(s) on duty <u>K</u> i	irsten Dohlen	and Brian F	edorko		

Dredge: <u>Eagle</u> One Project: Freeport Entrance Channel, TX DAILY REPORT Load Numbers 664 - 684 Date 16 / AUG / 2001 Area(s) Worked Sect. 4/3 StA. +50+00 60 -30+00 28.55 N 95.16 M Weather Conditions (incl. sea conditions) Least. #3-4 : Winds ! S to 2015 Range of Water Temp., Surface 29.5 C - 310 C Below Mid-Depth 29.5 C Condition and Effectiveness of Screening Screening condition good - hydraulic Il inflow boxes now in use, but high clay content NO Are there incidents involving endangered or protected species? YES Comments (details of turtle takes or whale sightings, dredged material, screening, biological by-catch, etc.): screening effectiveness. Buth mid boxes generally due to dogging. Surgassym, Bryozoa, Small Egg Case (Shark Eye-Yolinices Yenhaden (Brevoortia patronus) (1) Atlantic

(1) 7-5kirt	(1) 4th Tumber	ckle; Plastic Salt Box (1); Metal Waste (3)
		(1) Sweat pants, (2) Swings Nets; (2) Mesh Bogs
Wads of M	onofilament w/ les	eduts \$ hooks; 10 ft wire 3 Various lengths of
rope (to 10	0 ft); (1) Hefal	Dem. (1) Plastic Boroy, (1) underwear, Wire Rope.
		h., (1) Tow Strap, +1 Shrimp Net w/ TED.
		Bridge Watch Summary
Species	# of Animals	Time / Location / Comments
visiops truncatu	s 10-20	0700 - Grp. of 5-7 e end of yettes. Grp. of 10-20
		inside & outside jetties all afternoon til 2010 NR
		Another are of 10-12 load 673. Best guess for
		Another grp. of 10-12 load 673. Best gress for minimum # individual dolphus today \$ 10-20.
		·
Observer(s) on duty	Klirsten Dohlen	and Brian Fedorko

Dredge: <u>Eagle One</u> Project: <u>Freeport Entrance</u> Channel, TX

Date	AUG /2001	Load Numbers _	685 -	705	
Area(s) Worked Sect.	3/4/5/6 STA -40	+00 to+72+00;	-190+00 to-14	10+00 ² 8°55	N 95°16W
Weather Conditions (i	incl. sea conditions) <u>La</u>	rly a.m. winds	S to 15kts.1	Yostly Ckar	N 95°16 W P.A. Winds A to P.Cloudy Beauto + 2
Range of Water Temp	o., Surface <u>29.5-3/</u>	Belo	w Mid-Depth	29.5-3	31.5°C
	veness of Screening	,		_ /	
	y open w/ no		1 1		_
Both aft be	oxes generally	provide fair	rly effect	ive so	creening.
Are there incidents i	nvolving endangered of	or protected species	s? Y	ES	NO
Comments (details of	turtle takes or whale sig	ghtings, dredged ma	terial, screenin	g, biologic	al by-catch, etc.):
* No turtle	takes or sign	htings today	<u></u>		
	o is the first			15-	Material is
a thick	muddy silt u	of some sar	nd Clay	balls	are smaller
	et inflow box				
	by-catch today				
	identified Fish (
	bris included); (5) Metal
					esh Produce Bras;
	d debris; (6)				
	Wire rope; 12'				
(1) Cloth Ma	Levil; (5+) Wad	s of Monofilan	rent line w	/ hours	& lead wts.
(1) Fiberak	_		, , , , , , , , , , , , , , , , , , ,		
	<u> </u>	Bridge Watch Summ	nary		
Species	# of Animals	Time / Location	/Comments		
Tursiops tinneatus	15-25	Polphins are	observed	both in	iside à outside.
		the jettres,	in and ar	ound t	he channel
		throughou	t the a	lay-	he channel
				· · · · · · · · · · · · · · · · · · ·	
Observer(s) on duty	Kirsten Dohlen	and Brian	Fedorko		
` ' ' ' ' ' ' ' ' ' ' ' ' ' ' ' ' ' ' '					

Dredge: <u>Eagle One</u>
Project: <u>Freeport Entrance</u> Channel, TX

Date	G / 2001	Load Numbers	106-723	
Area(s) Worked Secr.	6 3/4 4/5 StA-110+C	0 to-190+00; -40+	00 to +72+00 28'5	5 N 95°16 W
Weather Conditions (inc	l. sea conditions)	ent #2 \$ 3 : Wind	ls:58-15kts;5	ties: PCloudy-14. Clear
Range of Water Temp.,		_	_	
Condition and Effectives				
	_			
to vary from the dredged	mterial.	9	9	
THE MILES	Tipe College			
Are there incidents inv	olving endangered o	r protected species?	YES	NO
Comments (details of tu	rtle takes or whale sig	htings, dredged mate	rial, screening, biolog	ical by-catch, etc.):
* Material in :	Sec. 5 /s gene	cally a thick	Mud/silt M	ix while other
				clay and sitt.
* No turtles	were sighted	today.		
* Biological "a			included sa	rgassum,
bryozoa	and (16) E	els (species d	midentified-	hopper).
* Abiotic debri				
	,			(4) Shring Net
	ff Chain; Sa	_		
	Filament Line; Mi.			
-	e! Msc. Rope			•
(5) Rocks		77.3		, 0,
	. <u>F</u>	Bridge Watch Summa	ry	
Species	# of Animals	Time / Location /	Comments	
Tursisps truncatus	14-21	Dolphins are	seen frequent	1/y throughout
		the day as	d throughout	the work area
		in groups	ranging in SIZ	e from 1-15.
		No obvious	dredge dolphin	the work area e from 1-15. interactions today
			0 /	
Observer(s) on duty	Kirsten Dohlen	and Brian	Fedorko	

Project: Freegort Edware Channel TX

WEEKLY SUMMARY

	723
Dates	nbers <u>576-724</u>
	-Depth <u>19-31.5 C</u>
Areas Worked (lat/longs, stations) Sec. 1, 3, 4, 5, 6 / Station	5: -90+00 to -190+00 ;-40+00 to +72+0
Are there incidents involving endangered or protected species?	YES
Comments (turtle takes, whale sightings, effectiveness of screening, by-c	atch, material, other info):
* No turtle takes and no turtle sighting	s this week.
* Screening condition improved to "a as the hydraulic rams for both	enerally good "this week
were installed. Although these mia	l boxes are usually
passed dire to close med-load.	screening effectiveness
has increased this week as the	Aft inflow boxes
remain closed more regularly.	
Tierrain Silving	
* Details of by catch and absorbe debis he each DALLY REPORT this week.	ave been listed on
* EAGLE 1 began dredging in Section 5	this week.
Bridge Watch Summary	
Date Various Species and Respective Number	Comments
12 Aug Tursiages trumatus: 19-29	Polphias are seen each
13 / AUG " 10-18	day in and around the channel and disposal area.
14 AVG " 12-22 15 AVG " 21-32	Numbers reported are
16 AUG " 10-20	made not to count the
17 AUG. " 15-25 18 AUG. " 14-21	same individuals twice
10 100	
Observers on duty Kirsten Doblen + Brian Foderko	

Dredge: <u>Eagle One</u> Project: <u>Freeport Entrana</u> Channel, TX

Date 19 / AUG / 2001 Load Numbers 724 - 741
Area(s) Worked Sea: 13,4,5,6 StA - 190+6 - 140-, -40-6 20-; +35-677278.55 N 95.16 W
Weather Conditions (incl. sea conditions) ? Cloar Cloudy BSS 2142 wirds 5 8.18
Range of Water Temp., Surface 28-31'C Below Mid-Depth 28 - 31'C
Condition and Effectiveness of Screening All boxes tirretional though tire note still present in flow
of 45 mid willow versioning. Stienmonness communes to vary from bood to good due to
Chapping with clay especially in sections land 6.
Are there incidents involving endangered or protected species? YES (NO)
Comments (details of turtle takes or whale sightings, dredged material, screening, biological by-catch, etc.):
Dredged material in sections 146 is largely chart with some silf, inaterial in
SECTIONS 34 and 5 is charteilt with some sand and grushed shell. Boxes continue to
chos duning booking, but is generally improved with approx 50% screening or recon
. zhoul
Biological by-coatch includes: (1) eets surgaisoner bryoson Atlantic Cutlassifish (Trichials
One sub-adult a adult laggerhead (Co-esta comme) was asserved outside the dig were.
Debris includes: plastic waste, styring ruts (12) would debris golf balls most bags (18)
pur pipe, tire, mire rape (20') metal whate rock, mornditarnow, wire rape (over 40')
pue pipe, the come con metal master is more than the
Bridge Watch Summary
Species # of Animals Time / Location / Comments
Tursiops transatus 4 0751 - Mouth of jettle
Titronatus 3.4 OB21- busy 5
Carcha carche 1 sub-adult ur odul 1253. in dump acca, att 518 law, headed NW
Terencotes 10-20 1200 - 2000 freeding them brown 3+5 to life stadion
Observer(s) on duty Kinsten Dohlen and Brian Fedorko

Dredge: <u>Eagle One</u>
Project: <u>Freeport Entrance</u> Channel, TX

Date 20 / AUG	/ zoo1	Load Numbers 742 - 76	2	
\rea(s) Worked Sect.	1,5,6 StA. +46	to th + 72 to = 190th - 140th,	28°55 N 95°16 W	
Weather Conditions (incl. s	ea conditions) M.	Clear - H. Claudy 54-12	73SS 2-3	
		Below Mid-Dep		
Condition and Effectivenes	s of Screening <u>Scr</u>	recting is generally in	proved, with approximately	50%
		Ray screening still two o		
		re opened ofter informing		
Are there incidents involv	ing endangered o	or protected species?	YES	
Comments (details of turtle	takes or whale sig	thtings, dredged material, scree	ening, biological by-catch, etc	.):
Dredged material	is silt and	day with some sand	+ chusted strell in secti	54 h 2010.
Boxes often chap wi	th clay, espe	cially in sections 6 +1.		
	sh lures fishing	uesh bags plante de	· · · · · · · · · · · · · · · · · · ·	' '
	E	Bridge Watch Summary		
; Species	– # of Animals	Time / Location / Commen	ts	
Tursings truncatus	b	0715-0720 - Sa +46 +4	'and 10W intersection	- ,
Showstophus meleagris	500-(000)	0830 - viside jette		
1. truncatus	15-20	, 🔾	lvery active across,	churrend
Observer(s) on dutyKir	Sten Dohlen	and Brian Fedorko		

Dredge: <u>Eagle One</u>
Project: <u>Freeport Entrance</u> Channel, TX

Date 21 / AUG / 20	or Load Numbers <u>763 - 782</u>
	StA -190-to-to-140to ; +40to + +72to 28.55 N 95.16 W
	tions) M. Clar - P. Clardy; 55-10=> SE 5-10; BST 2-3
	50°C - 31.5°C Below Mid-Depth 30°C - 31.5°C
	ening Approx l'xi hale remains in STB mid inflowscreening,
	as before, with 50% screening in Sections 4+5 and
	Section 6 due to clay content.
Are there incidents involving end	angered or protected species? YES NO
Comments (details of turtle takes or	whale sightings, dredged material, screening, biological by-catch, etc.):
Drectard material is si	+ + clay with some sond + shell Clay content
,	s depth increases, resulting in reduced screening
effectiveness as boxes clay	9
Biological by-catch include	Les: Sargassum, bryozon, eels (un i 1.1), lightning whelk
	ium), Sabal palmetto, Stomolophus nucleagnis,
Debris includes surae me	etal, wood, rope, monatilament plantic bags, mesh produce bogs
	inup met fragments fishing weights a lures, plastic debris
Tipergials, salt vap, chair,	wire rope, anchor, cloth,
	Bridge Watch Summary
Species # of Ani	mals Time / Location / Comments
Tursiops trucky 15-	25 dolphin leding, bouriding + socializing + throughout the
	Freeport sik.
Observer(s) on duty hirsten	Dohlen and Brian Fedorko

Dredge: <u>Eagle</u> One Project: <u>Freeport Entrance</u> Channel, TX

ate 22 / AUG / 2001 Load Numbers 783 - 803
182(5) Worked Seat. 4,5,6 Sta-190th -140th +40th + 172th 28:55 N 95:16 W
Teather Conditions (incl. sea conditions) P. Claudy 55-10 855 23
ange of Water Temp., Surface 30°C-31.5°C Below Mid-Depth 30°C-31.5°C
and tion and Effectiveness of Screening 1'x1' hale remains in 518 who inflow screening. Effectiveness
impains as about 50% in sections 465 and 0% in section 6 due to heavy clagging
ith day
The there incidents involving endangered or protected species? YES
iomments (details of turtle takes or whale sightings, dredged material, screening, biological by-catch, etc.):
Dredged material is silt and clay with some sand & shell, Clay increases as depth
icreases in all sections, resulting in changing of infland boxes. Boxes are opened & eleaned
fire notifying observed One sub-adult Caruta courte was observed from the
ridge on the most of the Jettier surrounded by Stornolophur male cari (bridge summan).
Biological by-catch includer: Bryosoa, Surgassum, ests (un : 2. d), S. Melengeis (ther
Ke often Many on the well decks today Sea whip (leptogorges virgilate) Busylas
ontrarium
Debris includes: shring nets, tires rock, fabric, plante wast, word, capper tubing rope,
anofilament, steel, Aberglass for ball cap plate stropping, sail convas, crease soul
is ruber,
Bridge Watch Summary
Species # of Animals Time / Location / Comments
thuncatus 15-25 Feeding + socializing throughout the arma, all day
-risate magnificant 19 1900 - wer channel
Stomolophus melcoopis saleral thousand isours in channel, Inac jothic to dump
areta cousta 1 subadult 1708 - in midst of 5 meleggs at mouth of jetters
Disserver(s) on duty Kirsten Dohlen and Brian Fedorko

Dredge: <u>Eagle One</u>
Project: <u>Freeport Entrance</u> Channel, TX

Date 23 / Aug	/ 2001	Load Numbers 804 - 820
		to-125th; 40th to 72th 28°55 N 95°16W
		Char; 5 5-10; BSS 2-3
		Below Mid-Depth 30-31-c
		cl' hole remains in 5th mid inflaw screening. Screening
		prox 402; in xetions 146, there is no inflaw screening
due to keavy slay lo		
Are there incidents invo	olving endangered (or protected species? YES NO
Comments (details of tur	tle takes or whale sig	ghtings, dredged material, screening, biological by-catch, etc.):
Dredged moterial	is sitt, clay, so	and 4 shell; day content increases in all sections as
depth increases. Infle	on poxes are e	sperced + chancel during looding withour adequate
opportunity to check	for biological to	ak es.
Biological by-rate	h includes: Sargo	ssum, bryezon, eels (un it'd in happer), S. meleagris
		loads), Leptogargia virgulata, Crassactrea virginica,
Sabal palments		
,		
Debris ixcludes: s	thrimp nets, plan	tic milk crotes 5 gallon buckers mesh bags
	•	sets, wood, metal debris, rubber hase, rubber
	•	n cars hard hat, cartires
,	,	,
]	Bridge Watch Summary
Species	# of Animals	Time / Location / Comments
T. truncatus	15-25	all day fall area / feeding, Socializing, bow-rising
Stomolopkus Mcleagris	(00015	throughout the day from jettles to dump.
	l	1 7 1 5 lock
Observer(s) on duty	lirsten Vonlen	and Brian Fedorko

Dredge: Eagle One

Project: Freeport Sixtronce Channel, TX

Date 24 / Aug	/ 2001	Load Numbers 821	-829	
Area(s) WorkedSect - 2,3	34,5 STA60to	to tioton; thoto to this	28°55 N	95°16W
Weather Conditions (incl.	sea conditions) M.Cla	ear; S 5-10; B55	 Q	
Range of Water Temp., S	urface 30-31	Below Mid-	Depth 30-31°C	
Condition and Effectivene	ess of Screening <u>1' x 1</u>	hole renuavis in or n	rid inflant Screening	g effectiveness is
poor, ranging from	0% to 20% de	re to heavy clay land	ing. Boxes are of	Her openal
during boding du	to day and det	nis.		
Are there incidents invo			YES	NÓ
Comments (details of turn	tle takes or whale sigh	ntings, dredged material, s	creening, biological t	oy-catch, etc.):
Traderal make	rial 15 day, Sil.	t, sand + crushed she	Il, with increasi	ing amounts of
class as denth in	Mascs. Directions	s effectivered is re	hull terking as	5 ethoro and
made to "clours"	N" Sections 2+3.	The dradge dapa	vited for the true	il doce after
load #825 and	returned to us	ork in the channel	at 1755H 6	Load # 826.
Biological by	condi indisoa	1 Sargassun		
Dobnis: Rocks	wood, shring not	s, Ath nots scrap i	ruetal, plastic d	about puc Pipe
wesh bags, rope,	plastic oulk by			
10000				
	E	Bridge Watch Summary		
Species	# of Animals	Time / Location / Con	nments	
Species				
_ / (10ccay)				
	-			
Observer(s) on duty	Livston Dahler	+ Bran Fedorko		
, .		••		

Dredge: <u>Eagle One</u>
Project: <u>Freeport Entrance</u> <u>Channel</u>, TX

Date <u>25</u> / Aug	/2001	Load Numbers 830-846
Area(s) Worked 1,4,5,6	; Sta -190th to	-135 to and +40 to to +72 too; 28 55 N 95-16 W
· ·	•	ear - P. Cloudy; winds 5 1-210; BSS 2; afternoon showers
		Below Mid-Depth 30°C - 31°C
Condition and Effectivene	ss of Screening 1'x	I hole remains in sits mid screening inflow that. Screening
		and opprox 20% in sections 4+5.
Are there incidents invol	ving endangered o	or protected species? YES
Comments (details of turtle	e takes or whale sig	ghtings, dredged material, screening, biological by-catch, etc.):
Dredged materia	l is mostly da	4 with Silt, sond of constred shell. Infant bakes once
<u> </u>		open during digging due to chagging with day +
debris. Stb draghear	I not shocked o	tto bads #74244 as draggarm not brought on board
Debris includes, sh	rimp nets rock	bytotaa, un idid cels s plastic debris, manafilament, tires, mesh produce bags, lead weights with rope, chain, ponts book engine,
	F	Bridge Watch Summary
Species	# of Animals	Time / Location / Comments
Tursiops truncatus	15-25	feeding, socializing + bankiding, all day, all day, all day
Frigata magnificur	1 04	0750 - over channel
Observer(s) on duty <u>Kir</u>	sten Dohlen a	Brian Federko

Dredge: <u>Eagle One</u>
Project: <u>Freeport Entrance</u> (hannel, TX

WEEKLY SUMMARY

Dates 19 / AUG / 2001 - 25 / AUG / 2001 Load Numbers 741 - 846
Range of Water Temp., Surface 28.0 - 31.5°C Below Mid-Depth 38.5°C
Areas Worked (lat/longs, stations) (23 4, 5, 6; Sta 790 to 125 - 60 to 50 to 72 to
28°55N 95°16W
Are there incidents involving endangered or protected species? YES
Comments (turtle takes, whale sightings, effectiveness of screening, by-catch, material, other info):
Two loggerhead Sea turtles (Caretta caretta) were observed this week: a sub-adult or
adult sized C. corretta surfaced in the dump on 19 Aug; a sub-adult sized C. corrett was
observed in the nilst of a large group Concentration of Stamolyphus meleagnis (Connanball
july fish) at the mouth of the jettier on 22 Aug. Neither sea title had any apparent
interaction with the dredge.
Dredged material is mostly clay and silt with some sand and crushed shell
in sections 3,4+5. Inflow boxes continue to clay with clay. Mid inflow boxes are generally
opered during all loads, reducing screening efficiency to 50% at best. There is 0% screening in
sections 1+6, and openerally 15-25% in other sections as percentage of day increases STB mid 1'x1' hale
Bidogical by-catch includes: sargassum, bryosoa, eds (un idid), 5. meleagris, Leptogorgia virgulata
Crossostrea Virginica, Sobol polmetto, Busylon contrarium, Mercenaria compechiensis, Trichiuru
Lepturus
Debris includes: string nets rocks, plastic debris, marchilament, threst mesh bags skel trans
cail, wand scray metal lead weights, wire rupe, cheain, parity book origines, meetal whom, pre
pipe, rope, plaste milk jug, samuar sail, 5 galler bucker hand tires copper tribing + trails
Bridge Watch Summary
Date Various Species and Respective Number Comments
19/AUG Tusiops truncatur (15-25); C. caretta (1) 2 logger head sightings detuiled above
20 / AUG Thurscotus (15: 25); Sineleagis (540-1000) Battlemose dolphein generally
21 / Aug Titruncatus (15:25); C.coruna (17) Sinceleaguis; riding, Socializing from Turning
22 Aug T-truncator (15.25); S. rueleagis; riding, Socializing from turning
24 / Aug no sightings
25 Aug I, truncatus (15-25); Frigata magnificers (1)
Observers on duty Kirsten Johlan + Brian Fodorko

Dredge: EAGLE 1

Project: FREEPORT, TX
DAILY REPORT
Date 26 AUG 2001 Load Numbers 847 - 862
Area(s) Worked Sec. 1, 6, 3, 4, 5. Stations -1980 to 7300 -40+00 to +72+00
Weather Conditions (incl. sea conditions) Winds to 12kts from 5. Fautort #2-3. P. Cloudy.
Range of Water Temp., Surface 29.5-30.5°C Below Mid-Depth 29.5-30.5°C
Condition and Effectiveness of Screening Condition is good. Effectiveness is not
Generally zero screening through and inflow boxes.
Are there incidents involving endangered or protected species? YES
Comments (details of turtle takes or whale sightings, dredged material, screening, biological by-catch, etc.): * Shal dragarm generally not brought on board most brought on board (both arms) trad #852 due to short sump run" - Thereted by observer from well deck. * Material & the same - run, chy, some shell debis. I sand * Robonical by-catch today included bryonage, sargassum, (1) Eel, and several cannomball pllyfish on well decks * Abothe debus included rocks, word debris, 50+ ft x 1.5° were rope, rubber tire, 15 ft rubber hose, Mesh produce bag shing net surgs, rope, (1) aluminum pipe, and were rope sorry
Species # of Animals Time / Location / Comments Tursings fruncatus 8-12 All afternoon in read account Chennel Cannonbull Tellytisk 100's In Channel all afternoon Observer(s) on duty KIRSTEN DAHLEN BRIAN TEDORKO

Project: FREEPORT, TX - FINAL -DAILY REPORT Load Numbers 863 - 842 Area(s) Worked 1, 6, 3, 4, 5 < Sections = Stations = - 190+00 to - 130+00; -20+00 to + 72+00 Weather Conditions (incl. sea conditions) Bearfort #2 to 3. Rainflightman furnds @ 0600. Winds 5 changing to N. Below Mid-Depth 30°-31°C Range of Water Temp., Surface 30-31°C Condition and Effectiveness of Screening Condition continues to be "generally good Both mid inflow boxes confince to be open throughout all Yours due to clogging. Aft boxes are often opened occasionally NO Are there incidents involving endangered or protected species? Comments (details of turtle takes or whale sightings, dredged material, screening, biological by-catch, etc.): * This is the final day of work in the FREEPORT CNANNEL. * Material is unchanged, generally mud/sitt w/ clay and some sand. * No weekly summary will be submitted for 26-27 Avanst. * Abrotic debus today included: Thung Net scraps, Golf Bell(1) Rocks, 45+ x 1 m. Wilt Rope, Fabric Scrap, Rope, Wood Debris, Hesh Produce Bry * Biological by-catch today included: sorgassum, bypeson, anid' I ed, Brevoortia Stod draghead not brought on deck after most loads today. - Hechanial Problems Bridge Watch Summary (went Fearings) Species # of Animals Time / Location / Comments Tursiags truncatus 24-30 All day, beginning 0940 - throughout channel, iside & nutsid Cannorball Telletist 1000's 1045 -> afternoon - In channel, in \$ out of jetties. Observer(s) on duty BRAN FEDORKO KIRSTEN DAHLEN

ENDANGERED SPECIES OBSERVER PROGRAM

Dredge: EAGLE /